From glowbugs@devp214.theporch.com Sun Feb 16 17:45:04 1997

Return-Path: <glowbugs@devp214.theporch.com>

Received: from devp214.theporch.com (devp214.theporch.com [192.150.244.22])

by uro.theporch.com (8.8.5/AUX-3.1.1)

with ESMTP id RAA00479 for <shimshon@theporch.com>;

Sun, 16 Feb 1997 17:45:02 -0600 (CST)

From: glowbugs@devp214.theporch.com

Received: from devp214.theporch.com (localhost [127.0.0.1]) by devp214.theporch.com (8.8.4/SCO-5.0.2) with SMTP

id XAA00444; Sun, 16 Feb 1997 23:43:35 GMT

Date: Sun, 16 Feb 1997 23:43:35 GMT

Message-Id: <199702162343.XAA00444@devp214.theporch.com>

Errors-To: ws4s@infoave.net

Reply-To: glowbugs@devp214.theporch.com Originator: glowbugs@devp214.theporch.com Sender: glowbugs@devp214.theporch.com

Precedence: bulk

To: Multiple recipients of list <glowbugs@devp214.theporch.com>

Subject: GLOWBUGS digest 448

X-Listprocessor-Version: 6.0 -- ListProcessor by Anastasios Kotsikonas X-Comment: Please send list server requests to listproc@theporch.com

Status: 0

GLOWBUGS Digest 448

Topics covered in this issue include:

1) Trade HW-16 for DX-60B by Jeffrey Herman <jeffreyh@hawaii.edu>

2) Yoop!

by "Brian Carling" <bry@mail1.mnsinc.com>

3) Jeffrey Herman

by "Brian Carling" <bry@mail1.mnsinc.com>

Date: Sat, 15 Feb 1997 18:25:55 -1000 From: Jeffrey Herman <jeffreyh@hawaii.edu> To: Boatanchors List <boatanchors@theporch.com>

Subject: Trade HW-16 for DX-60B

Message-ID: <Pine.GS0.3.93.970215182325.12512D-100000@uhunix3>

Hi Gang - I've got an HW-16 that I'd like to trade for a DX-60B. I'd rather go back to a seperate T-R setup than use a transceiver. The 16's manual is a photocopy. 73,

Jeff KH2PZ

Date: Sun, 16 Feb 1997 06:53:52 +0000

From: "Brian Carling" <bry@mail1.mnsinc.com>

To: glowbugs@theporch.com

Subject: Yoop!

Message-ID: <199702161452.JAA07417@news2.mnsinc.com>

Hi everyone. Seems quiet here. Where did you all go??

I have an interesting project I have been working on here. It's a 5763 to a 6146 with bandswitching 80-40-20-15-10m coverage. 800V B+ and a series regulator providing 180V for the screen.

I had to build a bias circuit since the 22.5 + 22.5V battery was long since deceased when I got it!

Having done that, I set about resolving the other problems. A broken dropping resistor for the screen supply - replaced that with a 4K 5 watt job (not enough power rating for the 8 watts, so need to replace it soon! Pulled out the neutralization NPO ceramic trimmer that was ARCing badly! Replaced it with two parallel #14 insulated wires, and added a decent choke made from 4 turns around a 47 ohm 1 watter right up by the plate cap on the 6146. That settled things down a LOT as far as some of the parasitics I had been getting...

Now I am using the good old 7050 kHz crystal and not raising anyone due to my bad co-ax(!) but I notice a slight Y00P as I key this thing and I want to get rid of that! I measure the screen supply at 185 key-up and about 182V key-down. Not too bad or is it?

I also took a look at the BIAS supply, and it measures -45V key up and climbs to -62V key-down, with some delay.

The idling current also does some odd things. It normally sits at about 5mA plate curent with the B+ turned on, but if I leave it turned an and the key is up, the plate current climbs to 20 mA and sits there!

Does this make any sense? Does it give anyone a clue as to what I need to do to cure the YOOP? Bear in mind it is only a very slight yoop of a few Hertz and rather slow, not too chirpy.

Yours for clean GLOWBUG signals -

Bry, AF4K

XXX	****************	XXXX	XXXX	××
***	73 from Radio AF4K / G3XLQ in Gaithersburg,	MD	USA	*
**	E-mail to: bry@mnsinc.com			*
***	See the great ham radio resources at:			*
**	http://www.mnsinc.com/bry/			*
***	·*************************************	***	***	**

Date: Sun, 16 Feb 1997 14:00:59 +0000

From: "Brian Carling" <bry@mail1.mnsinc.com>

To: glowbugs@theporch.com Subject: Jeffrey Herman

Message-ID: <199702162200.RAA29626@news2.mnsinc.com>

Does anyone know what has become of KH2PZ, Jeffrey Herman? jherman@hawaii.edu doesn't work any more. His ISP reports that he is not a user any more.

Does anyone know Jeff's new address???

Reply to bry@mnsinc.com